

HomeVision-Pro 3.5

Custom Solutions, Inc.

Copyright 2004-2006

Custom Solutions, Inc.
P.O. Box 33905
Indialantic, FL 32903
csi@csi3.com
www.csi3.com

VERSION HISTORY OVERVIEW

3.3 (1 June 2003)

Original release of HomeVision-Pro software and PROM.

3.3a (4 July 2003)

New PC software that corrects bug in version 3.3 in variable command entry screen. For commands that used two variables, the screen would sometimes display the wrong variable.

3.42b (1 July 2004)

New PC software and PROM making primarily the following changes:

- Support for "custom lighting" commands.
- The software now supports a serial port baud rate of 57,600.
- The standard HomeVision serial communications protocol can now be used over the add-on serial ports.
- Added more commands for reading data received from a serial port.
- Added commands to allow calculating a checksum value on data transmitted out a serial port.
- Added ability to detect and take action when any "standard" infrared signal is received.
- Added infrared commands to allow transmission of signals loaded into a "test" area.
- Allowed both RCS X-10 and serial thermostats to be used at the same time.
- Added option for serial ports 3 and 4, to receive any binary data.
- Added infrared commands to allow repeated transmission of IR signals.

3.42c (22 August 2004)

New PC software that corrects a bug related to how it exports data to an "HVConfiguration.txt" file. This file is only used with the Macromedia Flash movie that can be used to control HomeVision-Pro.

3.43(3 June 2005)

New PC software and PROM making the following changes:

- A few text fields in the software were widened to show more characters when the user has the Windows font size set to the "large" or "extra large".
- Made slight improvement to X-10 transmission collision avoidance. With the new design, if another device transmits an X-10 signal very shortly before HomeVision-Pro is ready to transmit a signal, there is less chance of a collision.
- Modified the digital temperature sensor reading to work with the new, slower DS18S20 sensors. Previously, there could be occasional errors reading these sensors if the HomeVision-Pro schedule file ran extremely fast.
- Allows "X-10 sequences" to include a wildcard character, which allows it to match any device or function code.

3.43a (12 June 2005)

New PC software that corrects a bug in the Thermostat Configuration Screen that could cause it to crash.

3.45 (5 December 2006)

New PC software and PROM making the following changes:

- Daylight savings time uses the new start and stop dates that begin in 2007 for the United States.
- The "auto report feature" has been improved.
- Added a web browser to the software.
- Modified the web pages to use "Cascading Style Sheets".
- Added a web page to display status of and control custom lights.
- Modified the "Run Program" command that can be transmitted to a PC serial port.
- The "Export" function under the file menu now includes custom lights in the ".HVX" file that it generates.
- Added a command to reset the controller.
- Added commands to reinitialize the serial port 3 and 4 chips.