Solder side Possible Block out Version 0.5a



Ensure ram cannot be written to whebn PHI2 is low